

# Oil Field Environmental Incident Summary

**Incident:** 20150611144830      **Date/Time of Notice:** 06/11/2015 14:48

**Responsible Party:** THUNDERBIRD RESOURCES LP

**Well Operator:** THUNDERBIRD RESOURCES LP

**Well Name:** WATSON B N34-11-1H

**Field Name:** RANCH CREEK

**Well File #:** 25123

**Date Incident:** 6/11/2015      **Time Incident:** 12:40

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 146

**Rng:** 99

**Sec:** 11

**Qtr:**

**Location Description:**

**Submitted By:** Wayne Smith

**Received By:**

**Contact Person:** Wayne Smith  
9400 N. BROADWAY #600  
OKLAHOMA CITY, OK 73114

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2 Mile

**Distance Nearest Water Well:** 2 Mile

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	8	Barrels	8	Barrels		
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Only produced salt water was released. Complete containment and removal of the water by vacuum truck

**Areal Extent:**

Completely contained within the trench.

***Potential Environmental Impacts:***

None, liquids removed and impacted area flushed with fresh water, also removed by vacuum truck

***Action Taken or Planned:***

Complete containment. Removal of all liquids by vacuum truck, disposal of produced water at licensed facility. Impacted ground flushed with fresh water.

***Wastes Disposal Location:*** waste consists of diluted produced salt water. Hauled to produced water licensed disposal facility.

***Agencies Involved:*** NDIC Field Inspector Nicole Nelson contacted and incident reported via telephone 6/11/15

***Updates***

---

***Date:*** 6/11/2015    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Crowdus, Kory

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.